



Instruction for installation:

Step 1: To have the cable ① passing through the hole of the base mount ② and the base ③

Step 2: Separately plug each of the 3 wire leads ① into each of the 3 terminals ⑧

Step 3: Fasten the base ③ and the base mount ② to the hull of ships with 3 screws M5x36L ⑥

Step 4: Secure the cable ① with the strain relief cap ④ to the base ③ with the screw M3x10L ⑤

Step 5: Connect the cable with socket ⑨ coming from the housing ⑩ to the cable & jack ⑦ in the base

Step 6: Fasten the housing ⑩ to the base ③ with the flat washer ⑪ and the nut ⑫

Step 7: Clip the top cover ⑬ to the housing ⑩