



**HEAVY DUTY LOADS**

**REMOTE KEY SWITCH**

**INPUT**

**INPUT**

**OUTPUT**

**OUTPUT**

**RED  
GREEN  
BLACK**

**LED**

**ON/OFF SWITCH**

**BATTERY**

THESE TWO CABLES MUST BE TERMINATED INTO WAGO PLUG

IT IS IMPERATIVE THAT THE NEGATIVE (BLACK) FOR THIS UNIT IS TAKEN FROM THE SAME BATTERY THAT THE MD IS ISOLATING. FAILURE TO DO THIS WILL CAUSE THE UNIT TO WORK ERRATICALLY. ONLY ONE NEGATIVE MUST BE SUPPLIED TO EACH UNIT FOR CORRECT OPERATION.